




MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director



Inspection Report Minerals Regulatory Program

Report Date November 9, 2005

Mine Name: Gold Queen/Million Dollar Gu	ulch	h
---	------	---

Operator Name: Martinique Mining

Inspector(s): Paul Baker

Other Participants: Buzz Rakow (Hanksville BLM)

Mine Status: Inactive

Permit number: S/017/035

Inspection Date: September 13, 2005

Time: 4:20-4:50 PM

nactive	Weather: Mostly clear, 70's			
Elements of Inspection	Evoluated	Comment	F	

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	\boxtimes	\boxtimes	
2. Public Safety (shafts, adits, trash, signs, highwalls)	\boxtimes	\boxtimes	
3. Protection of Drainages / Erosion Control			
4. Deleterious Material			
5. Roads (maintenance, surfacing, dust control, safety)			
6. Concurrent Reclamation			
7. Backfilling/Grading (trenches, pits, roads,			
highwalls, shafts, drill holes)			
8. Water Impoundments	\boxtimes	\boxtimes	
9. Soils			
10. Revegetation			
11. Air Quality			
12. Other	\bowtie	\bowtie	

Purpose of Inspection:

I was in the area and wanted to become familiar with the site.

Inspection Summary:

1. Permits, Revisions, Transfer, Bonds

On June 6, 2005, the Division approved a surety in the amount of \$3,384 for 0.53 acres of disturbance. This is based partly on a letter from the operator dated September 29, 2004, which says, "We have completed reclamation of over half of the previous disturbed area in the lower portion of the notice or permit area which included the previous permit holder mill site and pond area." Included with the letter was a copy of a disturbed area map created by the Division, and notes on the map indicate about two-thirds of the disturbed area was reclaimed in 2003. This map showed a disturbed area of 1.51 acres.

2. Public Safety (shafts, adits, trash, signs, highwalls)

This is a placer operation where the operator mines and processes alluvial materials. Some of the banks that have been mined are vertical or nearly so, and one near the upper end of the site (Photo 3) has been undercut. There is evidence this was done by someone with hand tools and not by the operator.



ATTACHMENT

Photographs

S/017/035, Gold Queen/Million Dollar Gulch, Martinique Mining Inspection Dated: September 13, 2005; Report Dated: November 9, 2005




Photo 1. There was not a lot of equipment at this site.




Photo 2. This is looking down toward the ponds. Note the steep sides of the gulch which could be backfilled with material from the ponds.



Photo 3. An undercut bank that needs to be resloped, even if mining operations continue in this area.





Photo 4. A breach in one of the ponds can be seen near the center of the photo. Note the steep sides of the gulch and the amount of erosion. Some of this erosion has been occurring since many years ago.



Mine Name: Gold Queen Million Dollar Gulch Township 31 S Range 11 E Section 28 SLBM Mine Number: S0170035



Acres Disturbed Acres Regraded Acres Seeded Road Acres Disturbed


Acres Released Acres Excluded Acres PreExisting Acres Prelaw

0

Total Acres Distrubed

Legend All items symbolized in legend may not be appear on map --- Township or range line: location Township or range Line --- Main Dirt Road

DOQ imagery date 1993





Dept. of Natural Resources Division of Oil, Gas, and Mining Mineral Mines Program

Different data sources and input scales may cause misalignment of data layers. This product may not meet DOGM standards for accuracy and content. Verify Scale

1:7,500 1 inch equals 625 feet